



NOTIFICATION TO THE GENERAL PUBLIC

DESCRIPTION OF ACTIVITY

Brunei LNG experienced an operational upset this evening, 01 June 2026, and the normalization process is currently in progress, actively managed by our teams.

IMPACT ON THE PUBLIC

The public may observe visible flaring and black smoke from our plant. These are controlled and expected outcomes of our operational upset and pose no risk to the surrounding community or environment.

POSSIBLE HAZARDS

There are no injuries, asset damage, or safety threats to people, the community, or the environment.

MITIGATION MEASURES

Brunei LNG internal designated teams are actively managing the situation and working towards operational recovery and resuming normal operations soon.

NAME OF THE DUTY HOLDER AND ADDRESS IN BRUNEI DARUSSALAM OF THE FACILITY

- Duty Holder: Public Information Officer (PIO)

For enquiries/concerns regarding this activity, please contact +673 7390446.



NOTIFIKASI KEPADA PENDUDUK AWAM

HURAIAN AKTIVITI

Brunei LNG telah mengalami gangguan operasi pada malam ini, 01 Jun 2026, dan proses pemulihan sedang dijalankan secara aktif oleh pasukan kami.

KESAN KEPADA AWAM

Orang awam mungkin akan melihat pembakaran api dan asap hitam dari loji kami. Ini adalah hasil yang terkawal dan dijangka tidak akan menimbulkan sebarang risiko kepada komuniti atau alam sekitar.

BAHAYA YANG BERKEMUNGKINAN

Tiada kecederaan, kerosakan aset atau ancaman keselamatan kepada orang ramai, komuniti atau alam sekitar.

LANGKAH-LANGKAH MITIGASI

Brunei LNG sedang menguruskan keadaan secara aktif dan berusaha ke arah pemulihan operasi serta menyambung semula operasi seperti biasa dalam masa terdekat.

NAMA PEMEGANG DUTI DAN ALAMAT DI BRUNEI DARUSSALAM

- Pegawai Bertugas: Pegawai Perhubungan Awam (PIO)

Untuk sebarang pertanyaan mengenai aktiviti ini, sila hubungi +673 7390446.